

Submission number **2018_261**

ID **244**

1 | Countries concerned

Countries concerned* **Finland France Norway United Kingdom Belgium Italy Austria Ireland Denmark The Netherlands Cyprus Germany Portugal Spain Sweden**

Main Member State* **Sweden**

2 | Producer/Distributor submitting notification

The producer/distributor* **Is the Notifier**

Name or identification of the producer/distributor* **IKEA of Sweden AB**

Responsibility **Manufacturer**

Contact name* **Martin Belica**

Address* **Tulpanvägen 8**

Town/City* **Älmhult**

Postal code* **S-343 81**

Country* **Sweden**

Email* **martin.belica1@ikea.com**

Telephone* **+46 72-886 57 53**

Website **<https://www.ikea.com/se/sv/>**

Type* **- Manufacturer of the product
- Retailer
- Other person presenting himself as the manufacturer by affixing to the product his name, trade mark or other distinctive mark
- Importer of the product
- Other professionals in the supply chain**

3 | Product involved

Category*	Hobby/sports equipment
Sub-category	Bicycle
Trademark*	IKEA
Model name	SLADDA
Bar code	
Total number of products held	27000
Custom code	
Country of origin*	Sweden
Brief description*	The SLADDA is a grey, aluminum, one-speed bicycle that comes in both 26” and 28” models. The bicycle was sold from August 2016 until January 2018.
Detailed description	- SLADDA detailed description.pdf
Photo	- SLADDA image.jpg

4 | Risk assessment of the notifier

Description*	The SLADDA is equipped with a Continental belt drive system, a toothed belt drive, instead of a conventional chain drive. The Continental belt drive system consists of an 8 mm wide belt, a front plastic sprocket “eco 39” fitted to a Prowheel 170 mm aluminum crankset and a “CDS eco 20” plastic (with steel core) rear sprocket fitted to a SRAM AUTOMATIX internal gear hub with coaster brake. The CDS Belt can break or snap resulting in consumers falling from the unit. The defect poses a low risk.
Record of accidents	Eleven (11) worldwide reports of CDS Belt breakage, including only two (2) minor injuries - one involving minor scratches and the other a bruise.
Level of risk*	Low
Report document	- RA.pdf

5 | Corrective actions already taken or planned

Action*	Recall of the product from end users
Please specify	Recall for a full refund at the points of sale - IKEA stores. No proof of purchase required.
Scope of the actions*	Regional
Duration of the actions*	Temporary
Results of the actions	Withdrawal of the product from customers' possession.
Company taking action	IKEA of Sweden AB

Additional information **A global sale stop has been issued on January 2018 and the global recall will retrieve the affected articles from the customers for a full refund. No proof of purchase is necessary.**

6 | Company(ies) in the supply chain which hold affected products

Details of the COMPANY (IES) **No file(s) attached**

7 | Other

Language **No file(s) attached**